



Office of the
Executive Engineer,
Banjar Division
HPPWD, Banjar.

+91-1903-221031/Fax 221031

TO WHOM SO EVER IT MAY CONCERN

Building safety certificate

It is certified that the building of LA MONTESSORI SCHOOL AT KELHELI, P.O. BAJAURA, TEHSIL BHUNTAR DISTRICT KULLU (H.P) has been inspected by the Assistant Engineer, Bahaura. As per his visual inspection of the building, seems to be safe for running school classes for the academic year **2019-2020 (One Year)**. However structural stability cannot be ascertained due to non availability of structural drawings, grade of concrete and other specification required for the building construction as per ISI building code. This certificate is being issued purely on the basis of visual inspection and issuance of this certificate does not confer any legal and financial liabilities on the issuer please.

Place: - Banjar

Executive Engineer
Banjar Division
HPPWD, Banjar

No:- PW/KD-I/WA-I/Building Safety /2019:- 276-71 Dated:- 16.4-19

1. Copy forwarded to the Principal LA MONTESSORI SCHOOL AT KELHELI, P.O. BAJAURA, TEHSIL BHUNTAR DISTRICT KULLU (H.P) for information please.

2. Copy to the Assistant Engineer, Bajaura Sub Division HP.PWD. Bajaura w.r.t. his office letter NO.06 dated 16/04/2019 for information and necessary action.

Executive Engineer
Banjar Division
HPPWD, Banjar