

TO WHOM SO EVER IT MAY CONCERN

BUILDING SAFETY CERTIFICATE

Certified that the building of La Montessori School Dunkhara P.O. Jari Tehsil Bhunter Distt. Kullu H.P. has been inspected by the Assistant Engineer Shat Sub Division HPPWD Shat. As per his visual inspection the building seems to be safe to run school classes for the academic year 2020-21 under normal condition. However structural stability cannot be ascertained due to non availability of structural design, drawings and IS specification required for the building construction. This certificate is being issued purely on the basis of visual inspection and issuance of this certificate does not confer any legal and financial liabilities on the issuer please. Further no addition & alteration be carried out in the building and if any addition & alteration is required fresh safety certificate be obtained.



**Executive Engineer,
Kullu Division,
HPPWD Kullu.**

No.PW/KD/WA-I/Building/2020 1563-64

Dated:-23-5-2020

Copy to the Assistant Engineer Shat Sub Division HPPWD Shat with reference to his office letter No. PW/MSD/E-3/2019-21 dated 18.5.2020 for information and necessary action.

✓ Copy to the Managing Director(Op) Hadimba Education Society Dhalpur Kullu Distt. Kullu H.P.


**Executive Engineer,
Kullu Division,
HPPWD Kullu.**